

# Inspection Photos

API: 071-09685

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/30/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09685 | Date: 8/30/2019

## Inspection Photos



**Photo 1.** There is erosion along the main road leading to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09685 | Date: 8/30/2019



## Inspection Photos



**Photo 2.** Erosion channel has developed along the main road causing stormwater to flow down the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09685 | Date: 8/30/2019



## Inspection Photos



**Photo 3.** Sediment traps along the road have filled in with sediment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09685 | Date: 8/30/2019



## Inspection Photos



**Photo 4.** Facing south along the reclaimed access road. Operator sign remains.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09685 | Date: 8/30/2019



## Inspection Photos



**Photo 5.** Facing southeast along the reclaimed access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09685 | Date: 8/30/2019



## Inspection Photos



**Photo 6.** Facing southeast toward the location. Perennial vegetation is uniformly established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09685 | Date: 8/30/2019



## Inspection Photos



**Photo 7.** Facing east toward the location. Perennial vegetation is uniformly established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09685 | Date: 8/30/2019



## Inspection Photos



**Photo 8.** Facing east toward the location. A patch of noxious weeds was found where the arrow points to in the northwest portion of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09685 | Date: 8/30/2019



## Inspection Photos



**Photo 9.** Facing northwest toward the location. Perennial vegetation is uniformly established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09685 | Date: 8/30/2019



## Inspection Photos



**Photo 10.** Facing northwest toward the location. A patch of noxious weeds was found where re arrow points to in the south portion of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09685 | Date: 8/30/2019