

Inspection Photos
Location Name: Miracle 13-12 Pad
Location ID: 333299



Production facility



Wellheads

Inspection Photos
Location Name: Miracle 13-12 Pad
Location ID: 333299



Unplacarded concrete vault



Unplacarded Trans Cube

Inspection Photos
Location Name: Miracle 13-12 Pad
Location ID: 333299



Lube oil tank



Lube oil tank placard

Inspection Photos
Location Name: Miracle 13-12 Pad
Location ID: 333299



Unused equipment



Unused equipment

Inspection Photos
Location Name: Miracle 13-12 Pad
Location ID: 333299



Trash