

## Inspection Photos

Location Name: LILLI UNIT-68N58W /6SESE

Location #: 326799



**Photo #1**

**Lilli Unit 16-6 (05-123-13691) Wellsite**

**Temporarily Abandoned | TA**

**No sign or Emergency number posted**

*prior insp.*



**Photo #2**

**Lilli Unit 16-6 Wellsite**

**Temporarily Abandoned | TA**

**No sign or Emergency number posted**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name:** LILLI UNIT-68N58W /6SESE  
**Location #:** 326799



**Photo #3**  
**Lilli Unit 16-6 Wellsite**  
**Stained soil**  
**Unused Gas supply tank**  
**No sign or Emergency number posted**  
*prior insp.*



**Photo #4**  
**Lilli Unit 16-6 Wellsite**  
**Stained soil**  
**Unused Gas supply tank**  
**No sign or Emergency number posted**



**Inspection Photos**  
**Location Name:** LILLI UNIT-68N58W /6SESE  
**Location #:** 326799



**Photo #5**  
**Lilli Unit 16-6 Battery site**  
**Shut-down | Inactive**  
*prior insp.*



**Photo #6**  
**Lilli Unit 16-6 Battery site**  
**Shut-down | Inactive**

**Inspection Photos**  
**Location Name: LILLI UNIT-68N58W /6SESE**  
**Location #: 326799**



**Photo #7**  
**Lilli Unit 16-6 Battery site**  
**Emergency number NOT valid**  
*prior insp.*



**Photo #8**  
**Lilli Unit 16-6 Battery site**  
**Emergency number NOW valid**