


**Inspection Photos**  
**Location Name: UPRR 38 Pan AM "T" True #1**  
**Location ID: 322551**



**Photo #1 WH sign**



**Photo #2 WH bradenhead exposed at surface**

**Inspection Photos**  
**Location Name: UPRR 38 Pan AM "T" True #1**  
**Location ID: 322551**



**Photo #3 Weeds growing on loc.**



**Photo #4 Unused equipment on loc. Unmarked flowline riser.**

**Inspection Photos**  
**Location Name: UPRR 38 Pan AM "T" True #1**  
**Location ID: 322551**



**Photo #5 Locked Flowline riser not tagged on loc.**