

Inspection Photos
Location Name: Cleveland #3
Location ID: 318056



**Photo 1 WH No emergency contact sig. Unused equipment:
PU and assoc. parts.**



Photo 2 Unmarked Not LOTO 2" riser

Inspection Photos
Location Name: Cleveland #3
Location ID: 318056



Photo 3 Unused equipment: PU and assoc. parts



Photo 4 Unused equipment: PU and assoc. parts

Inspection Photos
Location Name: Cleveland #3
Location ID: 318056



Photo 5 Unused equipment: Electric panel meter has been pulled.