

Inspection Photos
Location Name: Grant Tank Battery
Facility ID: 446608



Location Sign



Partially buried produced water vessel being removed.

Inspection Photos
Location Name: Grant Tank Battery
Facility ID: 446608



Partially buried produced water vessel in open excavation.



Impacted soils and ground water observed in the excavation.