

Inspection Photos

Location Name: Mesa E1-797 pad

Location ID: #441653

Inspection Date: August 30, 2019



Photo #1 – Facility sign.



Photo #2 – Overview of separators, tank battery, pumps, and pump shed from northeast.



Inspection Photos

Location Name: Mesa E1-797 pad

Location ID: #441653

Inspection Date: August 30, 2019



Photo #3 – Filter pots and day tanks located north and east of tank battery. Red circle denotes open excavation area.



Photo #4 – Open excavations north of tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Mesa E1-797 pad

Location ID: #441653

Inspection Date: August 30, 2019



Photo #5 – Open excavation in southeast corner of pump shed.



Photo #6 - Open excavation(s) in southwest corner of pump shed. Red circle denotes open excavation area.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Mesa E1-797 pad

Location ID: #441653

Inspection Date: August 30, 2019



Photo #7 – Open excavation located west of tank battery .



Photo #8 – Trash inside of excavation from previous photo.



Inspection Photos

Location Name: Mesa E1-797 pad

Location ID: #441653

Inspection Date: August 30, 2019



Photo #9 – Hose stored on west side of tank battery had metal fittings in direct contact with liner on inspection date. Note de minimis accumulations of fluids and soil inside of tank battery.



Photo #10 – Storage of foam and metal scraps inside southwest corner of tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Mesa E1-797 pad

Location ID: #441653

Inspection Date: August 30, 2019



Photo #11 – Junk and unused equipment stored inside southeast corner of tank battery.



Photo #12 – Trailer pump, filter socks, and filter stock storage container on top of lined secondary containment located southeast of tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Mesa E1-797 pad

Location ID: #441653

Inspection Date: August 30, 2019



Photo #13 – Trailer pumps located east of tank battery lack secondary containment.



Photo #14 – Localized accumulations of oil-stained soil beneath trailer pump in previous photo.



Inspection Photos

Location Name: Mesa E1-797 pad

Location ID: #441653

Inspection Date: August 30, 2019



Photo #15 – View of fenced wellhead area, day tanks, diesel AST, and trailer pumps from North.



Photo #16 – View of heated horizontal separators, ECD, and day tank from northeast. Note localized accumulations of oil-stained soil NE of fenced separator area.

