

Inspection Photos
Location Name: Dinner # 6-2
Location ID: 323078



Photo #1 Well & Sign



Photo #2 Red PTA Tag

Inspection Photos
Location Name: Dinner # 6-2
Location ID: 323078



Photo # 3 Separator & Meter Run

Photo # 4 Produced water vault/pit

Inspection Photos
Location Name: Dinner # 6-2
Location ID: 323078



Photo #5 Tank Battery