

# *Inspection Photos*

*Loc#335150*

*Operator: Laramie*

*Inspection Number: 692401325*

*Inspection Date: 8/20/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Pipeline path as it runs to North.

August 20, 2019



Photo#2:  
Pipeline path as it runs to North along base of Cut Slope.

August 20, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie CC Loc#335404





Photo#3:  
Vegetation on Fill Slope.

August 20, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie CC Loc#335404