

Inspection Photos

Loc#334546

Operator: Laramie

Inspection Number: 692401328

Inspection Date: 8/19/19





Photo#1:
Overview of Location to Northeast.

August 19 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gunderson Loc#334546



Photo#2:

Drain, of flexible pipe; usually a temporary BMP, is inadequately sized.

August 19 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gunderson Loc#334546



Photo#3:
Stacked wattle; wattles are designed for low surface flows .

August 19 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gunderson Loc#334546



Photo#4:
Fill slope, view to Southwest .

August 19 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gunderson Loc#334546