

# *Inspection Photos*

*Loc#335404*

*Operator: Laramie*

*Inspection Number: 692401322*

*Inspection Date: 8/20/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to Southeast.

August 20, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie CC Loc#335404





Photo#2:  
Unused equipment on Location.

August 20, 2019





**Photo#3:**  
Flowline/pipeline from top of plateau to Location has not had trench properly filled in, stabilized or re-vegetated

August 20, 2019



**Photo#4:**  
Flowline/pipeline from top of plateau to Location has not had trench properly filled in, stabilized or re-vegetated