

# Inspection Photos

Location ID, Name: 336100, HSR-MULLER-63N65W 29NESE



Photo 1 05-123-16879 HSR-MULLER9-29A



Photo 2 Battery



Photo 3 Production Equipment