

Inspection Photos
Location Name: Henderson #2
Location ID: 405711



Colorado Oil and Gas Conservation Commission
40.5866, -103.73653, 4619.1ft, 37°
09/04/2019 13:39:42

Photo 1 – Pumping Unit



Colorado Oil and Gas Conservation Commission
40.58657, -103.73644, 4616.5ft, 333°
09/04/2019 13:40:00

Photo 2 – Wellhead Sign



Inspection Photos
Location Name: Henderson #2
Location ID: 405711



Photo 3 – Stained Soil at Gas Engine



Photo 4 – Stained Soil at Wellhead



Inspection Photos
Location Name: Henderson #2
Location ID: 405711



Photo 5 – Latrine near Access Road



Photo 6 - Protective guard around Pumping Unit crank arms has been installed.

Inspection Photos
Location Name: Henderson #2
Location ID: 405711



Photo 7 – Deadman Guide Anchors not marked



Photo 8 - Deadman Guide Anchors not marked