

**Inspection Photos**  
**Location Name: Hornung Tank Battery**  
**Location ID: 450910**



**Production facility**

**Inspection Photos**  
**Location Name: Hornung Tank Battery**  
**Location ID: 450910**



**Debris and weeds on 8/27/19**



**Debris and weeds on 9/9/19**



**Inspection Photos**  
**Location Name: Hornung Tank Battery**  
**Location ID: 450910**



**Weeds on 8/27/19**



**Weeds on 9/9/19**



**Inspection Photos**  
**Location Name: Hornung Tank Battery**  
**Location ID: 450910**



**Debris on 8/27/19**



**Debris on 9/9/19**

**Inspection Photos**  
**Location Name: Hornung Tank Battery**  
**Location ID: 450910**



**Debris on 8/27/19**



**Debris on 9/9/19**



**Inspection Photos**  
**Location Name: Hornung Tank Battery**  
**Location ID: 450910**



**Unused equipment on 8/27/19**



**Unused equipment on 9/9/19**