

Inspection Photos
Location Name: Kaline SWD 5
Location ID: 313162



Photo 1. No NFPA diamonds on tank labels.



Photo 2. Well shut in at time of inspection.