

Inspection Photos
Location Name: Cleveland #7
Location ID: 336113



Photo 1 WH. WH sign does not reflect current operator and has no emergency contact information.



Photo 2 unused equipment: PU and assoc.. parts

Inspection Photos
Location Name: Cleveland #7
Location ID: 336113



Photo 3 Unused equipment: PU and assoc.. parts