

Inspection Photos  
Location Name: Hladky-O'Gorman#4  
Location ID: 311331



Photo 1 WH. WH sing faded and not legible



Photo 2 at time of inspection flow lines off well head are closed.

Inspection Photos  
Location Name: Hladky-O'Gorman#4  
Location ID: 311331



**Photo 3 Unused equipment: Alum. piping and electric conduit.**