

Inspection Photos
Location Name: CECIL-66N64W /2NENE
Location #: 305248



Colorado Oil & Gas Conservation Commission
40.52082, -104.50941, 1439.0m, 272°
09/09/2019 03:49:45 PM

Photo #1
Cecil 41-2 (05-123-22707) Wellsite
Shut-In | SI
Weeds



Colorado Oil & Gas Conservation Commission
40.52241, -104.50879, 1432.0m, 237°
09/09/2019 04:14:32 PM

Photo #2
Cecil 41-2, 31-2 Battery
Shut-down | Inactive