

Location:	CPC 126 Amoco B#2
Line:	Well to Manifold
Technicians:	Matthew Ingve
Date:	8/13/2018
Time	Pressure (PSI)
10:55:20 AM	1.6
10:55:50 AM	2.8
10:56:20 AM	26.3
10:56:50 AM	81.7
10:57:20 AM	81.7
10:57:50 AM	81.6
10:58:20 AM	81.6
10:58:50 AM	81.6
10:59:20 AM	81.5
10:59:50 AM	81.6
11:00:20 AM	81.5
11:00:50 AM	81.6
11:01:20 AM	81.5
11:01:50 AM	81.6
11:02:20 AM	81.5
11:02:50 AM	81.5
11:03:20 AM	81.5
11:03:50 AM	81.5
11:04:20 AM	81.5
11:04:50 AM	81.5
11:05:20 AM	81.5
11:05:50 AM	81.5
11:06:20 AM	81.5
11:06:50 AM	81.5
11:07:20 AM	81.5
11:07:50 AM	81.5
11:08:20 AM	81.4
11:08:50 AM	81.5
11:09:20 AM	81.5
11:09:50 AM	81.5
11:10:20 AM	81.5
11:10:50 AM	81.5
11:11:20 AM	81.4
11:11:50 AM	81.5
11:12:20 AM	81.4
11:12:50 AM	81.4
11:13:20 AM	81.4
11:13:50 AM	81.4
11:14:20 AM	81.4
11:14:50 AM	81.4
11:15:20 AM	81.4
11:15:50 AM	81.4

11:16:20 AM	81.4
11:16:50 AM	81.4
11:17:20 AM	81.4
11:17:50 AM	81.4
11:18:20 AM	81.3
11:18:50 AM	81.4
11:19:20 AM	81.4
11:19:50 AM	81.4
11:20:20 AM	81.4
11:20:50 AM	81.4
11:21:20 AM	81.3
11:21:50 AM	81.4
11:22:20 AM	81.3
11:22:50 AM	81.3
11:23:20 AM	81.3
11:23:50 AM	81.4
11:24:20 AM	81.4
11:24:50 AM	81.4
11:25:20 AM	81.4
11:25:50 AM	81.4
11:26:20 AM	81.4
11:26:50 AM	81.4
11:27:20 AM	81.4
11:27:50 AM	81.4
11:28:20 AM	26.7
11:28:50 AM	16.2
11:29:20 AM	15.4
11:29:50 AM	13
11:30:20 AM	7.3
11:30:50 AM	6.8
11:31:20 AM	1.7
11:31:50 AM	1.7

% loss over 30 minutes	0.49%	Less than 10%	Yes
% loss in last 5 minutes	0.12%	Less than 1%	Yes

Pass/Fail

Pass

