

Location:	CPC 126 Amoco B#3
Line:	Well to Manifold
Technicians:	Matthew Ingve
Date:	8/13/2018
Time	Pressure (PSI)
1:09:20 PM	1.7
1:09:50 PM	1.7
1:10:20 PM	1.7
1:10:50 PM	2.9
1:11:20 PM	3.7
1:11:50 PM	17.9
1:12:20 PM	79.5
1:12:50 PM	79.6
1:13:20 PM	79.6
1:13:50 PM	79.6
1:14:20 PM	79.6
1:14:50 PM	79.6
1:15:20 PM	79.6
1:15:50 PM	79.6
1:16:20 PM	79.6
1:16:50 PM	79.6
1:17:20 PM	79.6
1:17:50 PM	79.6
1:18:20 PM	79.6
1:18:50 PM	79.6
1:19:20 PM	79.6
1:19:50 PM	79.6
1:20:20 PM	79.6
1:20:50 PM	79.6
1:21:20 PM	79.6
1:21:50 PM	79.6
1:22:20 PM	79.6
1:22:50 PM	79.6
1:23:20 PM	79.6
1:23:50 PM	79.6
1:24:20 PM	79.6
1:24:50 PM	79.6
1:25:20 PM	79.6
1:25:50 PM	79.7
1:26:20 PM	79.7
1:26:50 PM	79.7
1:27:20 PM	79.6
1:27:50 PM	79.6
1:28:20 PM	79.6
1:28:50 PM	79.6
1:29:20 PM	79.6
1:29:50 PM	79.7

1:30:20 PM	79.7
1:30:50 PM	79.7
1:31:20 PM	79.7
1:31:50 PM	79.7
1:32:20 PM	79.6
1:32:50 PM	79.6
1:33:20 PM	79.6
1:33:50 PM	79.6
1:34:20 PM	79.6
1:34:50 PM	79.6
1:35:20 PM	79.6
1:35:50 PM	79.6
1:36:20 PM	79.6
1:36:50 PM	79.6
1:37:20 PM	79.6
1:37:50 PM	79.7
1:38:20 PM	79.7
1:38:50 PM	79.7
1:39:20 PM	79.7
1:39:50 PM	79.7
1:40:20 PM	79.7
1:40:50 PM	79.7
1:41:20 PM	79.7
1:41:50 PM	79.7
1:42:20 PM	79.7
1:42:50 PM	79.7
1:43:20 PM	79.7
1:43:50 PM	79.7
1:44:20 PM	79.7
1:44:50 PM	79.8
1:45:20 PM	79.7
1:45:50 PM	79.7
1:46:20 PM	79.7
1:46:50 PM	79.7
1:47:20 PM	79.7
1:47:50 PM	79.7
1:48:20 PM	79.7
1:48:50 PM	78
1:49:20 PM	44.6
1:49:50 PM	32.9
1:50:20 PM	34.1
1:50:50 PM	18.8
1:51:20 PM	7
1:51:50 PM	2.9
1:52:20 PM	2.4
1:52:50 PM	2.3
1:53:20 PM	2.3

% loss over 30 minutes	0.00%	Less than 10%	Yes
% loss in last 5 minutes	0.13%	Less than 1%	Yes

Pass/Fail

Pass

