

Location:	CPC 126 Amoco B#6
Line:	Well to Manifold
Technicians:	Matthew Ingve
Date:	8/13/2018
Time	Pressure (PSI)
3:12:10 PM	2.2
3:12:40 PM	2.2
3:13:10 PM	2.2
3:13:40 PM	2.1
3:14:10 PM	2.1
3:14:40 PM	85.8
3:15:10 PM	85.9
3:15:40 PM	85.9
3:16:10 PM	85.9
3:16:40 PM	86
3:17:10 PM	86
3:17:40 PM	86
3:18:10 PM	86.1
3:18:40 PM	86.1
3:19:10 PM	86.1
3:19:40 PM	86.1
3:20:10 PM	86.1
3:20:40 PM	86.1
3:21:10 PM	86.1
3:21:40 PM	86.1
3:22:10 PM	86.1
3:22:40 PM	86.1
3:23:10 PM	86.1
3:23:40 PM	86.1
3:24:10 PM	86.1
3:24:40 PM	86.1
3:25:10 PM	86.1
3:25:40 PM	86.1
3:26:10 PM	86.1
3:26:40 PM	86.1
3:27:10 PM	86.1
3:27:40 PM	86.1
3:28:10 PM	86.1
3:28:40 PM	86.1
3:29:10 PM	86.1
3:29:40 PM	86.1
3:30:10 PM	86.1
3:30:40 PM	86.1
3:31:10 PM	86.2
3:31:40 PM	86.2
3:32:10 PM	86.1
3:32:40 PM	86.2

3:33:10 PM	86.1
3:33:40 PM	86.1
3:34:10 PM	86.1
3:34:40 PM	86.1
3:35:10 PM	86.1
3:35:40 PM	86.1
3:36:10 PM	86.2
3:36:40 PM	86.2
3:37:10 PM	86.2
3:37:40 PM	86.2
3:38:10 PM	86.2
3:38:40 PM	86.2
3:39:10 PM	86.2
3:39:40 PM	86.2
3:40:10 PM	86.2
3:40:40 PM	86.2
3:41:10 PM	86.3
3:41:40 PM	86.3
3:42:10 PM	86.3
3:42:40 PM	86.2
3:43:10 PM	86.2
3:43:40 PM	86.3
3:44:10 PM	86.2
3:44:40 PM	86.3
3:45:10 PM	86.3
3:45:40 PM	86.2
3:46:10 PM	86.2
3:46:40 PM	86.2
3:47:10 PM	86.2
3:47:40 PM	86.2
3:48:10 PM	86.1
3:48:40 PM	86.1
3:49:10 PM	86.1
3:49:40 PM	86.1
3:50:10 PM	86.1
3:50:40 PM	86.1
3:51:10 PM	86.1
3:51:40 PM	86.1
3:52:10 PM	85
3:52:40 PM	1.7
3:53:10 PM	1.7
3:53:40 PM	1.2
3:54:10 PM	0.9

% loss over 30 minutes	0.00%	Less than 10%	Yes
% loss in last 5 minutes	0.12%	Less than 1%	Yes

Pass/Fail
Pass

