

Inspection Photos
Location Name: Barbara Jean 3-31
Location ID: 330986



Pic 1 stained soil



Pic 2 stained soil/ mechanical conditions

Inspection Photos
Location Name: Barbara Jean 3-31
Location ID: 330986



Pic 3 stained soil



Pic 4 trash