

Inspection Photos  
Location Name: Lauridson 2-A  
Location ID: 318088



Pic 1

Pic 2 unused equipment

**Inspection Photos**  
**Location Name: Lauridson 2-A**  
**Location ID: 318088**



COLORADO OIL AND GAS CONSERVATION COMMISSION  
40.04569, -104.92962, 5074.3ft, 348°  
09/09/2019 10:10:35



**Pic 3 venting wellhead**

**Video of leaking wellhead**