

## Inspection Photos

Location Name: 596-31A-65S96W 31NWNNE Pad

Location ID: #335875

Inspection Date: August 30, 2019



Photo #1 – Facility sign.



Photo #2 – Overview of separators on east side of location.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: 596-31A-65S96W 31NWNE Pad

Location ID: #335875

Inspection Date: August 30, 2019



**Photo #3 – Overview of tank battery on north side of location.**



**Photo #4 – View inside of tank battery secondary containment area at truck loadout.**



## Inspection Photos

Location Name: 596-31A-65S96W 31NWNE Pad

Location ID: #335875

Inspection Date: August 30, 2019



**Photo #5 – Trailer pump with secondary containment on north side of tank battery.**



**Photo #6 – View of fenced wellhead area from east side.**

**Note red well signs list outdated Marathon Emergency Contact Number, (866) 662-2378.**



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: 596-31A-65S96W 31NWN Pad

Location ID: #335875

Inspection Date: August 30, 2019



**Photo #7 –View of day tank and process pipe pump control area located north of wellheads.**



**Photo #8 – Uncapped, unmarked process piping observed north of wellheads.**

Note oil-stained soil described in previous FIR (doc #690200035) has been removed. No leaks were observed in this area during inspection.



## Inspection Photos

Location Name: 596-31A-65S96W 31NWE Pad

Location ID: #335875

Inspection Date: August 30, 2019



**Photo #9 – Overview of wellhead area from north. No audible gas leaks were detected in this area on inspection date.**



**Photo #10 – 596-31A-27 wellhead. Audible rattling was observed coming from plunger lift on inspection date.**

**Note: well cellars have been backfilled to prevent wildlife access.**



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources