

Inspection Photos
Location Name: Chevron-65S96W 596-31C Pad
Location ID: #335999
Inspection Date: August 30, 2019



Photo #1 – Facility sign.

Photo #2 – Overview of wellheads, looking south.

Note well cellars have been backfilled to prevent wildlife access.



Inspection Photos

Location Name: Chevron-65S96W 596-31C Pad

Location ID: #335999

Inspection Date: August 30, 2019



Photo #3 - Overview of wellheads, looking north.

Photo #4 – Chemical storage tank and process pipe pump controls located inside fenced wellhead area.

Note well cellars have been backfilled to prevent wildlife access.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Chevron-65S96W 596-31C Pad

Location ID: #335999

Inspection Date: August 30, 2019



Photo #5 – Overview of tank battery from southeast.



Photo #6 – View into east side of tank battery secondary containment.



Inspection Photos

Location Name: Chevron-65S96W 596-31C Pad

Location ID: #335999

Inspection Date: August 30, 2019



Photo #7 – View into west side of tank battery secondary containment.

Note trailer pump on top of lined secondary containment west of tank battery.



Photo #8 – Field photo dated 7/29/2019 illustrates outdated emergency contact number on well signs (866-662-2378).



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources