



Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Jul 2, 2019 5:06:52 PM MDT
Server Receive Date:	Jul 3, 2019 6:10:30 AM MDT
Reference Number:	20190702-18110680763
Location:	Unknown Location

Information

Name	celkins@gobrainstorm.net
Date	Jun 20, 2019
Well Name	FORD GAS UNIT D 1A
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Other Install Rock Run Down Repaired Berm

Photo of first corrective action completed



Completed work description Corrective Action 1

Well sign

Photo of second corrective action completed



Completed work description of corrective action 2

Erosion repair

Photo of third corrective action completed



Completed work description of corrective action 3  
Photo of fourth corrective action completed



Completed work description  
Completed work description of corrective action 4  
Additional photos



Summary of all work completed

Rock rundown

Re established berm  
Armored slope

Added more rock armor slopes and rundowns, built berm to divert water into rock and fixed the erosion channels on location