

Inspection Photos

Location Name: Booth USX EE 35-07D, 35-12D, 35-05D PAD

Location ID: 424917



Colorado Oil and Gas Conservation Commission
40.53562, -104.62831, 1456.2m, 154°
Sep 5, 2019 15:12:47

Photo 1: Tank Battery



Colorado Oil and Gas Conservation Commission
40.53563, -104.62788, 1458.4m, 221°
Sep 5, 2019 15:16:11

Photo 2: Weeds on location

Inspection Photos

Location Name: Booth USX EE 35-07D, 35-12D, 35-05D PAD

Location ID: 424917



Photo 3: Weeds inside berm (SE end of tank battery)



Photo 4: Weeds inside berm (South of tank battery)

Inspection Photos

Location Name: Booth USX EE 35-07D, 35-12D, 35-05D PAD

Location ID: 424917



Photo 5: Weeds