

**Inspection Photos**  
**Location Name: Pappenheim Pad**  
**Location ID: 322676**



**Photo 1: Tank Battery Sign**



**Photo 2: Location**

**Inspection Photos**  
**Location Name: Pappenheim Pad**  
**Location ID: 322676**



**Photo 3: Centralized Tank Battery**



**Photo 4: Weeds**





**Inspection Photos**  
**Location Name: Pappenheim Pad**  
**Location ID: 322676**



**Photo 5: Weeds/Hole in berm wall**



**Photo 6: Hole in berm wall**



**Inspection Photos**  
**Location Name: Pappenheim Pad**  
**Location ID: 322676**



**Photo 7: Unused equipment**