

Inspection Photos
Location ID, Name: 464139, NEWBY-63N68W-TANK 33NWSE



Photo 1 West Battery



Photo 2 Production Equipment



Photo 3 East Battery

Inspection Photos

Location ID, Name: 464139, NEWBY-63N68W-TANK 33NWSE



Photo 4 Production Equipment



Photo 5 LACT Units