

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/11/2019

Submitted Date:

09/11/2019

Document Number:

690004197

**FIELD INSPECTION FORM**

Loc ID 449884 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

15 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449881	WELL	PR	10/13/2018	OW	123-44563	NEWBY STATE 30N-34HZ	PR
449882	WELL	PR	10/21/2018	OW	123-44564	NEWBY 1N-33HZ	PR
449883	WELL	PR	10/21/2018	OW	123-44565	NEWBY STATE 26N-33HZ	PR
449885	WELL	PR	10/24/2018	OW	123-44566	NEWBY 27N-33HZ	PR
449886	WELL	PR	10/26/2018	OW	123-44567	NEWBY 28N-33HZ	PR
449887	WELL	PR	10/23/2018	OW	123-44568	NEWBY 2N-33HZ	PR
451358	WELL	PR	10/21/2018	OW	123-45087	NEWBY STATE 37N-4HZ	PR
451359	WELL	PR	10/21/2018	OW	123-45088	NEWBY STATE 16N-4HZ	PR
451360	WELL	PR	10/22/2018	OW	123-45089	NEWBY STATE 15N-4HZ	PR
451361	WELL	PR	10/13/2018	OW	123-45090	NEWBY STATE 34N-3HZ	PR
451362	WELL	PR	10/24/2018	OW	123-45091	NEWBY STATE 36N-4HZ	PR
451363	WELL	PR	10/13/2018	OW	123-45092	NEWBY STATE 38N-4HZ	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Shared battery services provided at location number: 464139				
Corrective Action:				Date:	

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	449881	Type:	WELL	API Number:	123-44563	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	449882	Type:	WELL	API Number:	123-44564	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	449883	Type:	WELL	API Number:	123-44565	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	449885	Type:	WELL	API Number:	123-44566	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	449886	Type:	WELL	API Number:	123-44567	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	449887	Type:	WELL	API Number:	123-44568	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451358	Type:	WELL	API Number:	123-45087	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451359	Type:	WELL	API Number:	123-45088	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			

Facility ID: 451360 Type: WELL API Number: 123-45089 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 451361 Type: WELL API Number: 123-45090 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 451362 Type: WELL API Number: 123-45091 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 451363 Type: WELL API Number: 123-45092 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

Routine inspection.

carlilec

09/11/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690004198	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934648">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934648</a>