

Inspection Photos  
Location Name: Sack #1  
Location ID: 319867



Photo 1 entrance to location. **WEEDS. Gauge hatch and Pressure relief valve venting.** See video

Photo 2 entrance to location. **WEEDS**

Inspection Photos  
Location Name: Sack #1  
Location ID: 319867



Colorado Oil and Gas Conservation Commission  
Sep 11, 2019 08:29:16

Photo 3 fuel gas to burner on separator is closed



Colorado Oil and Gas Conservation Commission  
Sep 11, 2019 08:29:25

Photo 4 **Weeds** around meter run.

**Inspection Photos**  
**Location Name: Sack #1**  
**Location ID: 319867**



**Photo 5 Weeds on location**



**Photo 6 Weeds on location**

Inspection Photos  
Location Name: Sack #1  
Location ID: 319867



Colorado Oil and Gas Conservation Commission  
Sep 11, 2019 08:32:16

Photo 7 TNK BTRY approx.. 55yrds from houses



Colorado Oil and Gas Conservation Commission  
Sep 11, 2019 08:32:48

Photo 8 TNK BTRY

Inspection Photos  
Location Name: Sack #1  
Location ID: 319867



Photo 9 PU, WH and well head sign




Photo 10 Stained soil around WH

**Inspection Photos**  
**Location Name: Sack #1**  
**Location ID: 319867**



**Photo 11 Weeds on location**



**Photo 12 Weeds on location.**

**Inspection Photos**  
**Location Name: Sack #1**  
**Location ID: 319867**



Colorado Oil and Gas Conservation Commission  
Sep 11, 2019 08:49:29

**Photo 13 weeds around PU**



Colorado Oil and Gas Conservation Commission  
Sep 11, 2019 08:49:56

**Photo 14 Weeds on location.**