



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Patrick Bateman (p.bateman@kosinm.com)
Submission Date: Jul 18, 2019 12:44:04 PM MDT
Server Receive Date: Jul 18, 2019 12:44:14 PM MDT
Reference Number: 20190718-18112037091
Location: Unnamed Road, Ignacio, CO 81137, USA
Jul 18, 2019 12:40:30 PM MDT [[View Map](#)]

Information

Name p.bateman@kosinm.com
Date Jul 16, 2019
Well Name SMITH GAS UNIT 01-20 FT 1
Select State Colorado
Work type COGCC Inspection AR
Action Complete Compliance Inspection Actions
Erosion Repairs
Grading of Well Pad

Photo of first corrective action completed



Completed work description Corrective Action 1

Wellsite sign

Photo of second corrective action completed



Completed work description of corrective action 2

Built erosional control silt trap

Photo of third corrective action completed



Completed work description of corrective action 3

Leveled pad

Photo of fourth corrective action completed



Completed work description of corrective action 4

Leveled pad continued

Additional photos



Summary of all work completed

Leveled pad and installed erosional control measures. Cleaned up all trash and debris from pad and checked signage.