

**Inspection Photos**  
**Location Name: Beebe Draw #1**  
**Location ID: 319335**



Colorado Oil & Gas Conservation Commission  
40.27853, -104.63667, 1425.0m, 178°  
09/11/2019 12:11:44 PM

**Production facility**



Colorado Oil & Gas Conservation Commission  
40.2789, -104.6366, 1408.0m, 197°  
09/11/2019 12:12:20 PM

**Wellhead**

**Inspection Photos**  
**Location Name: Beebe Draw #1**  
**Location ID: 319335**



**100 bbl condensate tank on 8/5/19**



**Equipment removed on 9/11/19**