

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/11/2019

Submitted Date:

09/11/2019

Document Number:

693501382**FIELD INSPECTION FORM**

Loc ID 319094 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
Carlisle, J	970-534-6006	COGCCInspections@extracti onog.com	ALL INSPECTIONS

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458188	WELL	DG	03/27/2019		123-48250	Coyote Trails 33W-15-8N	DG

**General Comment:**

**Inspected Facilities**

Facility ID: 458188 Type: WELL API Number: 123-48250 Status: DG Insp. Status: DG

**Complaint**

Comment: Inspection in response to complaint.  
 Field Inspector Assigned: Randy Silver  
 Complaint Received  
 Date: 09-04-2019  
 Complaint Contacted:  
 Date: 09-11-2019 Time: 10:00PM in person  
 Location ID #319094  
 Inspection Document # 693501380  
 Complaint Document #200448050  
 Nature of Complaint: Noise  
 Field Inspector Actions:  
 On 09-06-2019, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Noise. The complainant Monica Kober 1559 Hickory Dr Erie CO stated the issues were occurring outside of complainants home. She experienced a loud jet engine noise coming from the Coyote pad.  
 On 09-06-2019, I spoke with Complaint and asked if we could do a C scale sound study at her home she said yes. I Randy Silver and Supervisor Jason Gomez Set up sound study equipment behind her home where she stated the noise was coming from. I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, 09-11-19 the frac crew was rigging down, but did run all weekend and up until today. On 9-11-19, I Randy Silver and Supervisor Adam Kraich removed sound study equipment from complainants home and reviewed data. It was determined Extraction was in compliance with the C Scale sound study. Third party A scale sound study information was provided also, and Extraction was found to be in compliance with COGCC rules. Both sound studies are attached to complaint Document. At time of inspection, I spoke with (Company) drilling supervisor he stated at time of complaint they were drilling and no unusual activity was taking place.  
 Weather conditions: Clear location muddy in spots  
 See inspection document #693501380 per my inspection.  
 No violation of COGCC rules were observed at the time of the inspection.  
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
See Doc#693501380 and attached sound studies for full inspection	silverr	09/11/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693501383	A scale	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934907">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934907</a>
693501384	C scale	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934908">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934908</a>