

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402155968

Receive Date:

09/05/2019

Report taken by:

KRIS NEIDEL

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>WEXPRO COMPANY</u>	Operator No: <u>95960</u>	Phone Numbers
Address: <u>P O BOX 45003</u>		Phone: <u>(307) 352-7561</u>
City: <u>SALT LAKE CITY</u>	State: <u>UT</u> Zip: <u>84145-0601</u>	Mobile: <u>(307) 371-3610</u>
Contact Person: <u>April Stegall</u>	Email: <u>april.stegall@dominionenergy.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 10103Initial Form 27 Document #: 401224001

PURPOSE INFORMATION

- | | |
|----------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input checked="" type="checkbox"/> Other <u>Submittal of delineation plan, per COA of last approved F27</u> |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: <u>PIT</u>	Facility ID: <u>100667</u>	API #: _____	County Name: <u>MOFFAT</u>
Facility Name: <u>H.W. STEWART 1</u>	Latitude: <u>40.951129</u>	Longitude: <u>-108.322948</u>	
	** correct Lat/Long if needed: Latitude: <u>40.951540</u>	Longitude: <u>-108.322600</u>	
QtrQtr: <u>SWSW</u>	Sec: <u>32</u>	Twp: <u>12N</u>	Range: <u>97W</u> Meridian: <u>6</u> Sensitive Area? <u>No</u>

SITE CONDITIONS

General soil type - USCS Classifications SCMost Sensitive Adjacent Land Use Rangeland, Non-cropland, Oil and GasIs domestic water well within 1/4 mile? NoIs surface water within 1/4 mile? YesIs groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

149' from natural drainage, 5078' from nearest water well.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☒ **E&P Waste** ☒ **Other E&P Waste** ☐ **Non-E&P Waste**
- ☒ Produced Water ☐ Workover Fluids
- ☐ Oil ☐ Tank Bottoms
- ☐ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☒ Pit Bottoms
- ☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	GROUNDWATER	None	Visual inspection
Yes	SOILS	See analysis	Soil analysis
No	SURFACE WATER	None	Visual inspection

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Pit was previously backfilled. Historic Google Earth imagery indicates that the pit was closed some time between 2006 and 2011.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Core samples were obtained using a skid steer with auger attachment, in an attempt to obtain proper documentation for pit closure. One sample was taken, as sensory observations during sampling indicated that an exceedance was probable and soil sample most likely would not meet Table 910-1 requirements. Analysis (attached) shows that the sample did not meet Table 910-1 requirements for total TPH. Background (offsite) samples were not collected, as it's been previously established that high levels of arsenic are naturally occurring in the area. See attachments for previously tested high arsenic levels in the Powder Wash area. Please see the attachments for GPS coordinates of sample and soil observations made during sampling.

Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

A visual inspection was performed looking for signs of stained soil and potential leeching of pit components that may have impacted surface water or groundwater, none were found. Groundwater was not encountered during sampling.

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

A visual inspection was performed looking for signs of stained soil and potential leeching of pit components that may have impacted surface water or groundwater, none were found.

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

N/A

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 1

Number of soil samples exceeding 910-1 1

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 0

NA / ND

-- Highest concentration of TPH (mg/kg) 21700

NA Highest concentration of SAR

BTEX > 910-1 Yes

Vertical Extent > 910-1 (in feet) 8

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet)

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 910-1

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Wexpro Company will determine remediation based on size and impact upon the plugging and abandonment of the associated well.

REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

To be determined.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

☐ Ex Situ

_____ Excavate and offsite disposal
_____ If Yes: Estimated Volume (Cubic Yards) _____
_____ Name of Licensed Disposal Facility or COGCC Facility ID # _____
_____ Excavate and onsite remediation
_____ Land Treatment
_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Other _____

Groundwater Remediation Summary

☐ _____ Bioremediation (or enhanced bioremediation)
☐ _____ Chemical oxidation
☐ _____ Air sparge / Soil vapor extraction
☐ _____ Natural Attenuation
☐ _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

N/A, there is no indication that groundwater was impacted. If groundwater is encountered during remediation, COGCC will be notified immediately.

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☐ Annually ☐ Other _____

Report Type: ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report
☐ Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

REMEDATION COMPLETION REPORT

REMEDATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No _____

Do all soils meet Table 910-1 standards? No _____

Does the previous reply indicate consideration of background concentrations? _____

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? No _____

Does Groundwater meet Table 910-1 standards? Yes _____

Is additional groundwater monitoring to be conducted? No _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

To be determined.

Is the described reclamation complete? No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). _____ 05/01/2017

Date of commencement of Site Investigation. _____ 08/17/2017

Date of completion of Site Investigation. _____ 08/17/2017

REMEDIAL ACTION DATES

Date of commencement of Remediation. _____

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

Please see the attached delineation plan, as per the COA on document #401955339. Delineation to be completed upon approval of this Form 27. Results of delineation will be submitted via a subsequent Form 27 after delineation has been completed.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: April Stegall

Title: Reclamation Agent

Submit Date: 09/05/2019

Email: april.stegall@dominionenergy.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: KRIS NEIDEL

Date: 09/11/2019

Remediation Project Number: 10103

COA Type**Description**

	The sample that is collected from the "interval indicating the highest PID reading" should be analyzed for full COGCC table 910-1.
	It may be necessary to step out from the proposed 4 borehole locations around the pit to determine the lateral extent of contamination.
	COGCC EPS staff should be notified immediately, in the event that groundwater is encountered during investigation.
	This Site Investigation and Remediation Workplan (Form 27) is conditionally approved; however, additional information or activities may be required during the course of remediation.
	From Conversation with Wexpro Staff, April Stegall, the direct push rig will have the ability to drill deeper than 20 feet if necessary to define the vertical extent.. The Operator shall assess the nature and extent of contamination with confirmation soil samples and delineate the horizontal and vertical extent of contamination. If impacts exceed 20 feet in depth then the vertical extent shall be determined.
	Samples shall be analyzed for the complete Table 910-1 constituent list. The Operator may request a revised constituent list if they are able to demonstrate and provide justification for a reduced list.
	The Operator shall providing a minimum of 72 hours notice to Environmental staff Kris Neidel (kris.neidel@state.co.us) or 970-871-1963 prior to conducting field operations.
	The operator shall comply with Rule 910.b.3. The operator shall ensure that analytical laboratories use appropriate methods with detection limits less than or equal to the concentrations in Table 910-1.

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

402155968	FORM 27-SUPPLEMENTAL-SUBMITTED
402155973	OTHER

Total Attach: 2 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)