

FRAM OPERATING LLC – 10310

Location ID # 334480

API # 05-077-08932 Mansur 33-1

API # 05-077-09470 Mansur 33-1-L

API # 05-077-09471 Mansur 33-1-N

API # 05-077-09473 Mansur 33-1-G

API # 05-077-09475 Mansur 33-1-K

Inspection Date : 9/9/2019



GoogleEarth view of location area showing access road with entrance gate to location off Forest Service Rd 70 (FS.70).
Image date 6/17/2016.



GoogleEarth view of location area.
Image date 6/17/2016.

FRAM OPERATING LLC – 10310

Location ID # 334480

API # 05-077-08932 Mansur 33-1

API # 05-077-09470 Mansur 33-1-L

API # 05-077-09471 Mansur 33-1-N

API # 05-077-09473 Mansur 33-1-G

API # 05-077-09475 Mansur 33-1-K

Inspection Date : 9/9/2019



Location overview from SE corner looking W



Location overview from SE corner looking N

FRAM OPERATING LLC – 10310

Location ID # 334480

API # 05-077-08932 Mansur 33-1

API # 05-077-09470 Mansur 33-1-L

API # 05-077-09471 Mansur 33-1-N

API # 05-077-09473 Mansur 33-1-G

API # 05-077-09475 Mansur 33-1-K

Inspection Date : 9/9/2019



Location overview from SW corner looking N



Location overview from SW corner looking E

FRAM OPERATING LLC – 10310

Location ID # 334480

API # 05-077-08932 Mansur 33-1

API # 05-077-09470 Mansur 33-1-L

API # 05-077-09471 Mansur 33-1-N

API # 05-077-09473 Mansur 33-1-G

API # 05-077-09475 Mansur 33-1-K

Inspection Date : 9/9/2019



**API # 05-077-08932 Mansur 33-1 wellhead with sign.
Temporarily Abandoned. 800 psi on tubing gauge.**



**API # 05-077-09470 Mansur 33-1-L wellhead with sign and
pump jack. Temporarily Abandoned**

FRAM OPERATING LLC – 10310

Location ID # 334480

API # 05-077-08932 Mansur 33-1

API # 05-077-09470 Mansur 33-1-L

API # 05-077-09471 Mansur 33-1-N

API # 05-077-09473 Mansur 33-1-G

API # 05-077-09475 Mansur 33-1-K

Inspection Date : 9/9/2019



**API # 05-077-09473 Mansur 33-1G wellhead with sign.
Temporarily Abandoned.**



**API # 05-077-09471 Mansur 33-1-N wellhead with sign.
Temporarily Abandoned**

FRAM OPERATING LLC – 10310

Location ID # 334480

API # 05-077-08932 Mansur 33-1

API # 05-077-09470 Mansur 33-1-L

API # 05-077-09471 Mansur 33-1-N

API # 05-077-09473 Mansur 33-1-G

API # 05-077-09475 Mansur 33-1-K

Inspection Date : 9/9/2019



API # 05-077-09475 Mansur 33-1K wellhead with sign and pump jack. Temporarily abandoned



API # 05-077-09475 Mansur 33-1K wellhead with stained soil.

FRAM OPERATING LLC – 10310

Location ID # 334480

API # 05-077-08932 Mansur 33-1

API # 05-077-09470 Mansur 33-1-L

API # 05-077-09471 Mansur 33-1-N

API # 05-077-09473 Mansur 33-1-G

API # 05-077-09475 Mansur 33-1-K

Inspection Date : 9/9/2019



Combustor with pipe fence. Weeds.



Combustor controller and solar panel stolen.

FRAM OPERATING LLC – 10310

Location ID # 334480

API # 05-077-08932 Mansur 33-1

API # 05-077-09470 Mansur 33-1-L

API # 05-077-09471 Mansur 33-1-N

API # 05-077-09473 Mansur 33-1-G

API # 05-077-09475 Mansur 33-1-K

Inspection Date : 9/9/2019



Tank Battery



Weed debris on NE corner of tank battery

FRAM OPERATING LLC – 10310

Location ID # 334480

API # 05-077-08932 Mansur 33-1

API # 05-077-09470 Mansur 33-1-L

API # 05-077-09471 Mansur 33-1-N

API # 05-077-09473 Mansur 33-1-G

API # 05-077-09475 Mansur 33-1-K

Inspection Date : 9/9/2019



Meter housing on west side of tank battery. Unused chemical injector tank and chemical tank containment.



Unused chemical tank without containment on west side of meter housing.

FRAM OPERATING LLC – 10310

Location ID # 334480

API # 05-077-08932 Mansur 33-1

API # 05-077-09470 Mansur 33-1-L

API # 05-077-09471 Mansur 33-1-N

API # 05-077-09473 Mansur 33-1-G

API # 05-077-09475 Mansur 33-1-K

Inspection Date : 9/9/2019



**Closeup of unused chemical tank (3/4 full)
and trash 5 gal buckets.**



Trash and junk around meter housing.

FRAM OPERATING LLC – 10310

Location ID # 334480

API # 05-077-08932 Mansur 33-1

API # 05-077-09470 Mansur 33-1-L

API # 05-077-09471 Mansur 33-1-N

API # 05-077-09473 Mansur 33-1-G

API # 05-077-09475 Mansur 33-1-K

Inspection Date : 9/9/2019



Separator with pipe fence. Weeds.



Weeds and trash 5 gal bucket on E side of separator.

FRAM OPERATING LLC – 10310

Location ID # 334480

API # 05-077-08932 Mansur 33-1

API # 05-077-09470 Mansur 33-1-L

API # 05-077-09471 Mansur 33-1-N

API # 05-077-09473 Mansur 33-1-G

API # 05-077-09475 Mansur 33-1-K

Inspection Date : 9/9/2019



Trash lumber on S edge of location.



Erosion along W edge of separator fence.