

Inspection Photos
Location Name: Elton N Miller 'C' #2
Location ID: 318812



Photo #1 WH sign



Photo #2 WH



Inspection Photos
Location Name: Elton N Miller 'C' #2
Location ID: 318812



Photo #3 unused equipment.



Photo #4 unused equipment.

Inspection Photos
Location Name: Elton N Miller 'C' #2
Location ID: 318812



Photo #5 unused equipment.



Photo #6 gas meter, pig station

Inspection Photos
Location Name: Elton N Miller 'C' #2
Location ID: 318812



Photo #7 ECD, Hoz. Heated Separator.



Photo #8 TB

Inspection Photos
Location Name: Elton N Miller 'C' #2
Location ID: 318812



Photo #9 TB sign.

