

Inspection Photos  
Location Name: 1415 Corp C unit #1  
Location ID: 318165



Photo #1 WH sign



Photo #2 WH and PJ

Inspection Photos  
Location Name: 1415 Corp C unit #1  
Location ID: 318165



Photo #3 TB sign

Photo #4 TB

**Inspection Photos**  
**Location Name: 1415 Corp C unit #1**  
**Location ID: 318165**



**Photo #5 ECD**

**Photo #6 Gas meter**

Inspection Photos  
Location Name: 1415 Corp C unit #1  
Location ID: 318165





Photo #7 unused, unmarked risers no LOTO

Photo #8 unused, unmarked riser no LOTO

**Inspection Photos**  
**Location Name: 1415 Corp C unit #1**  
**Location ID: 318165**




**Photo #9 unused, unmarked risers no LOTO**

**Photo #10 unused, unmarked riser no LOTO**

**Inspection Photos**  
**Location Name: 1415 Corp C unit #1**  
**Location ID: 318165**



**Photo #11 unused, unmarked risers no LOTO**



**Photo #12 unused, unmarked riser no LOTO**

**Inspection Photos**  
**Location Name: 1415 Corp C unit #1**  
**Location ID: 318165**



**Photo #13 unused, unmarked risers no LOTO**

**Photo #14 unused, unmarked riser no LOTO**

Inspection Photos  
Location Name: 1415 Corp C unit #1  
Location ID: 318165




Photo #15 unused, unmarked risers no LOTO

Photo #16 Stained soil at base of WH

**Inspection Photos**  
**Location Name: 1415 Corp C unit #1**  
**Location ID: 318165**



**Photo #17 Stained soil under prod. plumbing**



**Photo #18 Stained soil at base of east crude oil tank on the backside.**

**Inspection Photos**  
**Location Name: 1415 Corp C unit #1**  
**Location ID: 318165**



**Photo #19 possible leak on east crude oil tank**

**Photo #20 weeds growing around PJ.**

Inspection Photos  
Location Name: 1415 Corp C unit #1  
Location ID: 318165



Photo #21 Content label faded on crude oil tanks



Photo #22 produced water tank.