

Inspection Photos
Location Name: Roy Dutcher unit B #1
Location ID: 317870



Photo #1 WH sign

Photo #2 WH and PJ

Inspection Photos
Location Name: Roy Dutcher unit B #1
Location ID: 317870



Photo #3 stained soil around WH



Photo #4 Electrical transformers, breaker panel and meter.

Inspection Photos
Location Name: Roy Dutcher unit B #1
Location ID: 317870



Photo #5 TB sign

Photo #6 TB

Inspection Photos
Location Name: Roy Dutcher unit B #1
Location ID: 317870



Photo #7 stained soil under crude oil valve

Photo #8 stained soil under crude oil tank valve possible leak at valve.

Inspection Photos
Location Name: Roy Dutcher unit B #1
Location ID: 317870



Photo #9 stained soil under crude oil valve possible leak at valve




Photo #10 Stained soil around unused unmarked riser. no LOTO on risers.

Inspection Photos
Location Name: Roy Dutcher unit B #1
Location ID: 317870




Photo #11 unused unmarked riser no LOTO.

Photo #12 unused equipment.

Inspection Photos
Location Name: Roy Dutcher unit B #1
Location ID: 317870




Photo #11 unused unmarked riser no LOTO. Stained soil around unused riser

Photo #12 unused equipment.