

**Inspection Photos**  
**Location Name: George H. Gerhardt #1**  
**Location ID: 336278**



**Photo #1 WH sign**



**Photo #2 WH and PJ**



**Inspection Photos**  
**Location Name: George H. Gerhardt #1**  
**Location ID: 336278**



**Photo #3 WH sign installed**



**Photo #4 Electrical transformers, breaker panel and meter.**

**Inspection Photos**  
**Location Name: George H. Gerhardt #1**  
**Location ID: 336278**



**Photo #5 TB sign no indication of wells it serves**

**Photo #6 TB.**





**Inspection Photos**  
**Location Name: George H. Gerhardt #1**  
**Location ID: 336278**



**Photo #7 unused, unmarked riser TO**



**Photo #8 Unused, unmarked riser TO.**

**Inspection Photos**  
**Location Name: George H. Gerhardt #1**  
**Location ID: 336278**



**Photo #9 unused, unmarked riser TO**



**Photo #10 Unused, unmarked riser TO.**



**Inspection Photos**  
**Location Name: George H. Gerhardt #1**  
**Location ID: 336278**



**Photo #11 unused, unmarked riser TO**



**Photo #12 Crude oil prod. manifold**

**Inspection Photos**  
**Location Name: George H. Gerhardt #1**  
**Location ID: 336278**



**Photo #13 gas meter**



**Photo #14 Heated Hoz. Sep.**