


**Inspection Photos**  
**Location Name: LILLI UNIT-68N58W /8SENE**  
**Location #: 326919**



**Photo #1**  
**Lilli Unit 8-8 (05-123-13862) UIC - Injection Wellsite**  
**UIC Annual Inspection**  
**Not Injecting - Gas**  
**Shut-In | SI**  
**Weeds**



**Photo #2**  
**Lilli Unit 8-8 UIC - Injection Wellsite**  
**Injection meter: 0 mcf**