

Inspection Photos
Location Name: LILLI UNIT-68N58W /7SENE
Location #: 326953




Photo #1
Lilli Unit 8-7 (05-123-13911) UIC - Injection Wellsite
UIC Annual Inspection
Not Injecting - Gas
Shut-In | SI
Weeds



Photo #2
Lilli Unit 8-7 UIC - Injection Wellsite
Well sign

Location #: 326953



Injection meter: 0 mcf