

Inspection Photos
Location Name: LILLI UNIT-68N58W /6SENE
Location #: 326943



Colorado Oil & Gas Conservation Commission
40.69322, -103.89785, 1442.0m, 252°
09/10/2019 04:14:42 PM

Photo #1

Lilli Unit 8-6 (05-123-13900) UIC - Injection Wellsite

UIC Annual Inspection

Not Injecting - Gas

Shut-In | SI



Colorado Oil & Gas Conservation Commission
40.69321, -103.89793, 1438.0m, 270°
09/10/2019 04:15:31 PM

Photo #2

Lilli Unit 8-6 UIC - Injection Wellsite

Injection meter: 0 mcf