



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Patrick Bateman (p.bateman@kosinm.com)
Submission Date:	Jul 31, 2019 11:48:22 AM MDT
Server Receive Date:	Jul 31, 2019 11:48:43 AM MDT
Reference Number:	20190731-18113189134
Location:	9 Rd 3227, Aztec, NM 87410, USA Jul 31, 2019 11:46:25 AM MDT [ <a href="#">View Map</a> ]

## Information

Name	p.bateman@kosinm.com
Date	Jul 16, 2019
Well Name	KENNEDY GAS UNIT A 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Contaminated Soils

Photo of first corrective action completed



Completed work description Corrective Action 1

Kennedy A2

Photo of second corrective action completed



Completed work description of corrective action 2

Cleaned up contaminated soil around production equipment.

Photo of third corrective action completed



Completed work description of corrective action 3  
Completed work description of corrective action 4  
Summary of all work completed

Fixed small erosional rilling not noted in inspection

.

Cleaned up and disposed of contaminated soil. Fixed erosional rilling that was not noted on inspection.