

Location:	CPC 248 Amoco A#3
Line:	Well to Separator
Technicians:	Bill Espinosa & Cody Baylis
Date	6/12/2019
Time	Pressure (PSI)
3:47:10 PM	1.8
3:47:40 PM	162.1
3:48:10 PM	162.1
3:48:40 PM	162.1
3:49:10 PM	162.1
3:49:40 PM	162.1
3:50:10 PM	162.1
3:50:40 PM	162.1
3:51:10 PM	162.1
3:51:40 PM	162.1
3:52:10 PM	162
3:52:40 PM	162
3:53:10 PM	162
3:53:40 PM	162
3:54:10 PM	162
3:54:40 PM	162
3:55:10 PM	162
3:55:40 PM	162
3:56:10 PM	161.9
3:56:40 PM	161.9
3:57:10 PM	161.9
3:57:40 PM	161.9
3:58:10 PM	161.9
3:58:40 PM	161.9
3:59:10 PM	161.9
3:59:40 PM	161.9
4:00:10 PM	161.9
4:00:40 PM	161.8
4:01:10 PM	161.8
4:01:40 PM	161.8
4:02:10 PM	161.8
4:02:40 PM	161.8
4:03:10 PM	161.8
4:03:40 PM	161.8
4:04:10 PM	161.8
4:04:40 PM	161.7
4:05:10 PM	161.7
4:05:40 PM	161.7
4:06:10 PM	161.7
4:06:40 PM	161.7
4:07:10 PM	161.7
4:07:40 PM	161.7

4:08:10 PM	161.7
4:08:40 PM	161.7
4:09:10 PM	161.7
4:09:40 PM	161.7
4:10:10 PM	161.7
4:10:40 PM	161.6
4:11:10 PM	161.6
4:11:40 PM	161.6
4:12:10 PM	161.6
4:12:40 PM	161.6
4:13:10 PM	161.5
4:13:40 PM	161.5
4:14:10 PM	161.5
4:14:40 PM	161.5
4:15:10 PM	161.5
4:15:40 PM	161.5
4:16:10 PM	161.5
4:16:40 PM	161.5
4:17:10 PM	161.5
4:17:40 PM	161.5
4:18:10 PM	161.4
4:18:40 PM	161.4
4:19:10 PM	161.4
4:19:40 PM	161.4
4:20:10 PM	161.4
4:20:40 PM	161.4
4:21:10 PM	161.4
4:21:40 PM	161.4
4:22:10 PM	161.4
4:22:40 PM	2.3
4:23:10 PM	2.3

Pass/Fail

% loss over 30 minutes	0.43%	Less than 10%	Yes		
% loss in last 5 minutes	0.06%	Less than 1%	Yes		Pass

