



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Aug 7, 2019 8:29:41 AM MDT
Server Receive Date:	Aug 7, 2019 8:31:22 AM MDT
Reference Number:	20190807-18113706340
Location:	557 Airpark Dr, Durango, CO 81303, USA Aug 7, 2019 8:29:03 AM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	Aug 2, 2019
Well Name	GEARHART GAS UNIT 01-06 FT 1
API Number	50670636200
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Other

Photo of first corrective action completed



Completed work description Corrective Action 1

Photo of second corrective action completed



Completed work description of corrective action 2

Sprayed scotch thistle populations.

Sprayed scotch thistle populations.

Photo of third corrective action completed



Completed work description of corrective action 3

Photo of fourth corrective action completed



Completed work description

Completed work description of corrective action 4

Additional photos



Additional photos

Sprayed canada thistle populations.

Sprayed musk thistle populations.

na



Completed work description
Summary of all work completed

Sprayed thistle populations in reclamation area.
sprayed noxious weeds