



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Aug 7, 2019 8:31:21 AM MDT
Server Receive Date:	Aug 7, 2019 8:33:02 AM MDT
Reference Number:	20190807-18113705646
Location:	557 Airpark Dr, Durango, CO 81303, USA Aug 7, 2019 8:32:33 AM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	Aug 2, 2019
Well Name	GEARHART GAS UNIT 01-05 FT 2
API Number	50670950300
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Other

Photo of first corrective action completed



Completed work description Corrective Action 1

Photo of second corrective action completed



Completed work description of corrective action 2

Sprayed musk thistle populations.

Sprayed musk thistle populations.

Photo of third corrective action completed



Completed work description of corrective action 3
Photo of fourth corrective action completed



Sprayed musk thistle populations.

Completed work description
Completed work description of corrective action 4
Additional photos



Sprayed musk thistle populations.
na

Completed work description
Summary of all work completed

Sprayed musk thistle populations in the reclamation area.
na