



## Form Information

Form Name: **Compliance Follow Up Form**  
Submitter Name: Patrick Bateman (p.bateman@kosinm.com)  
Submission Date: Aug 7, 2019 12:36:55 PM MDT  
Server Receive Date: Aug 7, 2019 12:37:11 PM MDT  
Reference Number: 20190807-18113736947  
Location: 3601 N 1st St, Bloomfield, NM 87413, USA  
Aug 7, 2019 12:36:49 PM MDT [ [View Map](#) ]

## Information

Name p.bateman@kosinm.com  
Date Aug 7, 2019  
Well Name SEIBEL GAS UNIT A 1  
Location Name (Other) Seibel A2  
Select State Colorado  
Work type COGCC Inspection AR  
Action Complete Compliance Inspection Actions  
Clean up Operator Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

Location sign

Photo of second corrective action completed



Completed work description of corrective action 2

Debris picked up as noted on inspection

Completed work description of corrective action 3  
Completed work description of corrective action 4  
Summary of all work completed

N/A

.

Picked up debris from location (valve). Checked erosion and other punch list items to ensure no new actions needed. Cleaned up all other trash and debris and disposed properly.