

Inspection Photos

09/11/2019

Operator: HOUSTON EXPLORATION
COMPANY* THE - 10068

Location ID: 411471

Yuma County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: HOUSTON EXPLORATION COMPANY* THE - 10068

Location ID: 411471



Photo 1: Photo taken from the south end of the location, facing north. Photo shows vegetation over the reclamation area.



Photo 2: Photo taken from the west end of the location, facing north. Photo shows perimeter fence remaining on location. Fence is in disrepair, is considered debris and requires removal.

