

Inspection Photos

09/11/2019

Operator: OMIMEX PETROLEUM INC - 66190

Location ID: 304971

Yuma County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos
Operator Name: OMIMEX PETROLEUM INC - 66190
Location ID: 304971



Photo 1: Photo taken from the location, facing north. Photo shows vegetation over the reclamation area.



Photo 2: Photo taken from the location, facing east. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator Name: OMIMEX PETROLEUM INC - 66190
Location ID: 304971



Photo 3: Photo taken from the location, facing south. Photo shows vegetation over the reclamation area.



Photo 4: Photo taken from the location, facing west. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator Name: OMIMEX PETROLEUM INC - 66190
Location ID: 304971



Photo 5: Photo taken from the southwest corner of the location. Photo shows one of the 3 anchors remaining on the location. Anchors were observed on the Northwest, Southwest and Southeast corners. Reclamation specialist did not observe an anchor on the northeast corner.



Photo 6: Photo of trash debris remaining.